



LEGEND

- VEW-1 ● Vapor extraction well, installed September 2001
- VMW-1 ▼ Vadoze zone monitoring well, installed September 2001
- ⊘ Former PVC vadose zone monitoring device, destroyed August 2000
- B-1 ▲ February and June 2000 exploratory borehole
- B-7 △ June 2000 exploratory bore and groundwater grab sampling location
- MW-1 ⊕ Monitoring well, installed August/September 2000
- Property line

Borehole and well locations are shown relative to features on a previous investigation report figure, and are approximate.

0 35
SCALE IN FEET



SITE PLAN, SOIL EXCAVATION AND WELL INSTALLATION LOCATIONS

1287 Fremont Avenue
Los Altos, CA

By: MJC

SEPTEMBER 2002

Figure 2



Stellar Environmental Solutions

Geoscience & Engineering Consulting